

APPENDIX

TITANIC SIGNATURE PROJECT
CONSTRUCTION PROGRESS PHOTOS
SEPTEMBER 2010

Titanic Signature Building Report Nr 8



Photo 1: View of North Elevation (as at 8/9/10)



Photo 2: View of South Elevation (as at 8/9/10)

Titanic Signature Building Report Nr 8



Photo 3: View of South East Corner (as at 8/9/10)



Photo 4: Hull 4 Roof Steel (Note: MBF in cherry picker working on cladding rails) (as at 8/9/10)

Titanic Signature Building Report Nr 8



Photo 5: Hull 4 Cladding Rail Brackets – Level 5 (as at 8/9/10)



Photo 6: Hull 3 Metal Decking & Concrete Infill – Level 5 (as at 8/9/10)

Titanic Signature Building Report Nr 8



Photo 7: Hull 1 Structural Steel at roof (note: metal decking in foreground) (as at 8/9/10)



Photo 8: NW Service Yard Ramp with up-stand wall partially cast. (As at 8/9/10)

Titanic Signature Building Report Nr 8



Photo 9: Basement -2 Blockwork – Circulation Corridor (as at 8/9/10)



Photo 10: Basement – 2 Blockwork: (As at 8/9/10)

Titanic Signature Building Report Nr 8



Photo 11: Outside Building Contract (NW Ramp in Construction from -1 to Ground) (as at 8/9/10)



Photo 12: Outside Building Contract (Plaza Slab – West Elevation) (as at 8/9/10)

Titanic Signature Building Report Nr 8



Photo 13 South Elevation (as at 30/9/10)



Photo 14 Hull 4 roof guttering (as at 30/9/10)

Titanic Signature Building Report Nr 8



Photo 15 Hull 4 Roof (as at 30/9/10)



Photo 16 View of Hull 4 Roof

Titanic Signature Building Report Nr 8



Photo 17 Roof view over Hull 1



Photo 18 North Elevation (As at 30.09.10)

Titanic Signature Building Report Nr 8



Photo 19 South Elevation (as at 30/9/10)



Photo 20 South West Corner (as at 30/9/10)