

RPII ANNUAL PLAYGROUND INSPECTION REPORT



NEW LODGE
PLAY AREA
BELFAST CITY COUNCIL
10th April 2013

This Inspection was carried out by Mel Campbell RPII Signed Mobile Home fall

Quality Assessment:

Site Name: New Lodge Play Area, New Lodge, BT15 2EQ

General Comments:

The play equipment is suitable for 1-12 year olds. The play area is showing signs of wear and is in immediate need of repair. The wet pour surface at the Multi Unit leg needs repaired as it is too hard and has sharp edges evident. See individual items for further details.

Date: 10/04/13

						Compliance to BSEN 1177	Assessment	Actions	Works
Item: Toddler Multi Unit Manufacturer: Sutcliffe Label: Wicksteed Age Range: 3 - 10 Capacity: 10 Surfacing: Red Wet Pour	2	N	М	Problem: This item is fire damaged and is missing panels Recommendation Replace all missing play panels and play items or as this item is in poor condition recommend full refurbishment Problem: Missing nut covers Recommendation Replace	2	Z	н	Multi Unit leg base have been cut and filled with cold tar. This is creating a hard surface and sharp edges within the falling space of this item – Remove leg bases Repair damaged wet pour under unit	2
Item: Cradle Swings Manufacturer: Wicksteed Label: Yes 2006 Age Range: 1 - 5 Capacity: 2 Surfacing: Red Wet Pour Overall Mean Score =	2	N	L	Problem: 2 missing swing seats and chains Recommendation Replace	2	Y	L	N/A	5

* Priority Action

1 Action Immediately (Contact Client)

2 Action within 1 month

3 Action within 3 months

4 Action within 9 months

5 Monitor

*Quality Score

Good = 10 Fair = 5 Poor = 2 N.B. Mean Score = total quality score divided by the number of items.

Quality Assessment:

Site Name: New Lodge Play Area, New Lodge, BT15 2EQ Date: 10/04/13

Item No.	Item Description	Inclusive for all Abilities Y/N	Quality Score	Compliance with BSEN 1176 Y/N	User Risk Assessment	Ad	ctions	Item Priority	Safety Surface Compliance to BSEN 1177	Surfacing Risk Assessment	Actions	Surface Priority Works
3		N	2	N	М		Problem: No barriers under platform Recommendation Barriers recommended under platform to remove possible entrapment	2	N	L		3
	Item: Senior Multi Unit Manufacturer: Sutcliffe Label: No Age Range: 4 + Capacity: 10 Surfacing: Red Wet Pour						Problem: Missing bridge and temporary panels Recommendation Replace missing bridge and remove temporary panels Problem: Rope is missing Recommendation Replace missing rope Recommendation				Repair 10x2m wet pour patch	
	all Mean Score =		2				This item requires major refurbishment					

N.B. Mean Score = total quality

* Priority Action

1 Action Immediately (Contact Client)

2 Action within 1 month

3 Action within 3 months

4 Action within 9 months

5 Monitor

*Quality Score

Good = 10 Fair = 5 Poor = 2

score divided by the number of items.

Quality Assessment:

ANCILLARY STRUCTURES

Site Name: New Lodge Play Area, New Lodge, BT15 2EQ

Date: 10/04/13

	AKT GTKGGTGKEG				
<u>TYPE</u>	GENERAL QUALITY CONDITION	<u>ACTIONS</u>	PRIORTY		
Boundary Fencing	10	N/A	5		
Gates	5	N/A	5		
Signs	2	Additional information required such as Playground Rules and an Emergency Telephone Number	3		
Bin	2	2 bins badly burnt - replace	2		
Seats/Benches	5	Remove trip hazard around kerb edges	3		
Paths	5	Replace item which has been removed from 2 bays	5		

OVERALL MEAN SCORE:

4.8

* Priority Action

1 Action Immediately (Contact Client)

2 Action within 1 month

3 Action within 3 months

4 Action within 9 months

5 Monitor

*Quality Score

Good = 10

Fair = 5

Poor = 2

N.B. Mean Score = total quality score divided by the number of items.