WR 4/16/0706

Oil Pollution at Woodburn Carrickfergus

 Call Received:
 27/03/2016 20:42:00

 Pollution Observed:
 27/03/2016 19:10:00

Investigation Date && Time 28/03/2016 11:15:00

Pollution Confirmed? True

Initial Severity Confirmed Severity

X Cor: Low Low

Y Cor:

PolluterConfirmed? False

Farm Bus ID:

Pollutant Category Oi

OIL Hydraulic fluid (mineral)

Source: Other
Pollutant Cause: Unknown

Fish Kill Severity: Kill Count

09 June 2016 Page 1 of 2

WR 4/16/0706

Oil Pollution at Woodburn Carrickfergus

Investigation Report

found only a very small quantity of mineral oil in a small waterway adjacent to where works had been ongoing. We notified staff on site but did not feel any other action was required.

WR 4/16/0780

Oil pollution from drilling site at Woodburn

Call Received:

10/04/2016 20:00:00

Pollution Observed:

Investigation Date && Time

11/04/2016 09:00:00

Pollution Confirmed?

True

Initial Severity

Confirmed Severity

X Cor:

Low

Low

Y Cor: 337801

391067

PolluterConfirmed?

True

Farm Bus ID:

Pollutant Category

Oil

OIL Other

Source:

Industry

Pollutant Cause:

Unknown

Fish Kill Severity:

Kill Count

WR 4/16/0780

Oil pollution from drilling site at Woodburn

Investigation Report

3 complainants reported on Sunday night having seen oil on Sunday afternoon (dry and sunny). Investigation on Monday morning

(wet day) found a small light film of oil running off the site from an area just inside the access gate and down the road along with some suspended solids being washed off the access lane (see photographs). The runoff was entering a waterway approximately 350m down the road. At this point there was no visible oil but there was still a cloudiness caused by the suspended

solids.