

-

Report to: Parks and Leisure Committee.

Subject: Flooding at Properties Adjacent to Cherryvale Playing Fields

Date: 13 March 2014

Reporting Officer: Rose Crozier, Assistant Director of Parks and Leisure

Contact Officer: Stephen Walker, Departmental Portfolio Programme Manager

1 Relevant Background Information

The purpose of this report is to bring to the attention of the Committee a recent incident at properties in Knockeden Park adjacent to Cherryvale Playing Fields which involved an urgent request for sandbags.

It was noted that the request by a resident had indicated that the flooding has been caused as a result of the runoff from Cherryvale Playing Fields. This could potentially impact on properties numbered 30 – 100 which is a distance of approximately 320m.

At this time it is not clear as to the exact cause, surveys are currently underway and a further report will be brought back to Committee in due course with recommendations on any necessary actions to remedy the situation.

2 Key Issues

The Committee is asked to note the following points:

- 1. There is a differential level between the playing fields and the private gardens at Knockeden Park;
- 2. There is an outlet pipe, which, as far as we can establish, is working;
- 3. There is a possibility that the water from the pitches is not being fed into the outlet pipe:
- 4. Further investigation is needed to establish whether there is a need for additional drainage to be installed to ensure that the rainwater is fed into the outlet pipe:
- 5. The installation of additional drainage for a length of approximately 320m, if necessary, would be costly.

3	Resource Implications
	Financial Implications

	1
	There are no additional costs at this time.
	Human Resources Implications
	There are no additional human resource implications at this time.
4	Equality and Good Relations Considerations
4.1	There are no equality implications
5	Recommendations
5.1	The Committee is asked to note the report.
6	Decision Tracking
An update report will be brought to Committee at a future date.	
7	Key to Abbreviations
l	
8	Documents Attached
Appendix A – Photograph of flooding at Knockeden Park	

Appendix A – Photographs of flooding







